

<p>1</p>	<table border="1"> <tr> <td>A</td> <td>rebated part with welded corners</td> </tr> <tr> <td>B</td> <td>sleeve part with welded corners</td> </tr> <tr> <td>C</td> <td>screw 3,9 x 38</td> </tr> <tr> <td>D</td> <td>screw 4,5 x 50</td> </tr> <tr> <td>E</td> <td>rubber seal</td> </tr> </table>	A	rebated part with welded corners	B	sleeve part with welded corners	C	screw 3,9 x 38	D	screw 4,5 x 50	E	rubber seal	<p>2</p>	
A	rebated part with welded corners												
B	sleeve part with welded corners												
C	screw 3,9 x 38												
D	screw 4,5 x 50												
E	rubber seal												
<p>A</p> <p>B</p>	<p>3</p>	<p>3.1</p> <p>A</p>	<p>3.2</p> <p>B</p>										
<p>4</p>	<p>5</p>	<p>6</p>	<p>7</p>										
<p>8</p>	<p>9</p>	<p>10</p>	<p>11</p>										

* hinge dependent